BAY TRE-EOS USERS GROUP





" Tandy Corp./Radio Shack Inc.

MARCH

???????

Mod? Mais oui, je suis le artiste modèle trois Le IBM? Je ne le connais pas.

#### SOUTH BAY TRS-80 USERS GROUP

Page - Contents 2. EDITOR'S NOTE

CONVERT BY GEORGE E. OLSON 3.

- 3. HOW SPEEDSW/CHD WORKS BY PETE FRATUS 5. SPEEDSW/CHD BY PETE FRATUS
- 6. OF MANUALS AND MYSTERIES BY EDITOR
- 6. MAIL CORNER ETC.

SBUG meetings are held the 3rd Tuesday of each month in the north-east corner of Dysan's building at:

Time - 7:15 to 10:30 PM

5401 Patrick Henry Drive Santa Clara, Ca

March 20, April 22, and May 24

Topic of the month: Not yet revealed by the Great Computer God who is currently contemplating his navel (located right next to the reset button, and sometimes confused with it).

Also !!! Don't forget the SIG group that meets at Dysan the first Wednesday of each moath (March 7th). The Model 100 is popular at this meeting. See you there!!!

#### MEMBERSHIP

If you would like to become a member of SBUG and start receiving our newsletter "Dynamic Memories" then send \$18.00 (check/money order) to the following address:

> South Bay TRS-80 User Group P.O. Box 60116 Sunnyvale, Ca 94088

or come to one of our meetings. If you also wish to communicate with our bulletin board system (SBUG-80) then include an additional \$25.00 for an account on the system. You must be a member of SBUG to have an account on SBUG-80. Please, include your address and phone number. Thanks . . . 

COPYRIGHT (C) 1983 SOUTH BAY TRS-80 USERS GROUP (SBUG). WORLD RIGHTS RESERVED. NO PART OF THIS PUBLICATION MAY BE REPRODUCED WITHOUT GIVING CREDIT TO THE AUTHOR AND SBUG. REPRODUCTIONS MAY ONLY BE PERFORMED BY NONPROFIT ORGANIZATIONS. PROFIT MAKING OGANIZATIONS MUST HAVE PRIOR WRITTEN PERMISSION OF THE EDITOR.

# YOUR STEERING COMMITTEE

	Member	SBUG-80 Username	I	hone
Discussion L	eaders:			
	Sabri Kawash	(SABRI)		
		(BREWER)	(408)	252-9332
	Casey Parker	(CASEY)	(415)	793-2715
Treasurer:		(0.000)	(,	.,,
	Glenn Vaughn	(TREAS)	(408)	259-5349
Nevaletter E		(/	(400)	23,-334,
	Joel Lee	(EDITOR)	(408)	926-3999
Assistant		(20000)	(400)	Edit
	Chuck Ward	(CHUCK)	(408)	245-7688
Librarians:		(0002)	(400)	243-7000
	Bernie Thompson	(BERNIE)	(408)	867-7455
(tage)	Gary Dixon	(GDIXON)		262-6937
(doc.)	Bill Jibby	(JIBBYTRM)		268-0181
SBUG-80 Syso		(010011111)	(400)	200-0101
	Robert Byrd	(EDITOR)	(408)	732-6775
	OTHER KEY I	NDIVIDUALS		
Cover Artist	.1			
	Dave Fox	(DAVEFOX)	(408)	374-5258
Public Relat	ions:	, ,	,,	
	Ron Carpenter	(RON)	(415)	726-3487
Host Compute		,,	(400)	
	SBUG-80	(EVERYONE)	(408)	737-SBUG
If the need	arises, feel free	to give one	of us	a call.

# THE EDITOR'S BYTES

My wife firmly believes that hardware manufacturers and software producers are united in a giant conspiracy to take from us computer hobbyists the very last of our tattered, grubby money, giving in return nothing but useless technology. Of course my wife is Latin American, and Latin Americans, when they are not busy seeing conspirators concealed behind park bushes or lurking under restaurant tables, are frantically conspiring.

Segue into whither we goest. Knowest thou? The Model I is ancient now, honored, but ancient. Surely, 40 years from now a monk on the windswept plains of Tibet will be attempting to write a program on his Model I that will reveal his karma, but for here and now, the end is in sight. The Model III will follow the same trail, Apparat no longer supports NEWDOS, so what computer and DOS will YOU be working with?

#### CONVERSION -- MOD III TO I

#### BY GEORGE E. OLSON

We know that Mod. I programs may be converted to a Mod. III, however there have been some doubts about converting Mod. III to Mod. I. This may be accomplished with the sid of DOSPLUS 3.5. First boot up DOSPLUS 3.5, then enter the following command:

CONVERT :1 :0,E,MOD1=N

Quoting from DOSPLUS page #3-7: "By specifying <MOD1=N>, we inform CONVERT that the diskette to be converted is NOT a Mod. I double density TRSDOS, and therefore must be a Mod. I TRSDOS.

I have converted several disks without any problems. The only problem that may occur is in case the program was written for Mod. III.

# HOW SPEEDSW/CMD WORKS by Pete Fratus, South Bay TRS-80 Users Group

There have been about a dozen letters and hints sent to the TRS-80 magazines about how to make your Model 4 run at 4MHz in Model III mode. None has given a solution to the occasional disk crashes caused by running at a faster speed during disk I/O. Ian Webb wrote a small program to handle the disk problem. From Ian's earlier work, I borrowed the code to make an enhanced version that handles another problem — how to get back to III speed without booting.

Why would I want to run in the slower Model III speed anyway? Several times I have run into an application that doesn't work well in the faster speed, such as the BASIC full screen editor from CAU. XEDIT allows configuration of key repeats. When a fast repeat is chosen and I am running at 4 speed, it is difficult to move the cursor only one character at a time.

# That makes editing tough!

Cassette loading and some games can also be a problem. Just about anything that runs off the clock works differently and sometimes not at all.

SPEEDSW/CMD is a small assembly language program that switches back and forth between Model III and Model 4 speed. It uses the same technique described in the Model III/4 Disk System Owner's Manual on page 80, Operating Speed.

By PEEKing or POKEing location 16912, (ORing) or (ANDing) a 64 or 191 to it, and OUTputting to port 236, the clock speed is changed back and forth from III to 4. The switching function of the program relies on the fact that the speed is always going to be one or the other. Just find out what it is now, and make it the opposite.

The disk timing part was a little trickier. Ian's program was loading a value into part of TRSDOS. I spent quite a while figuring out just exactly what he was doing. In the book, TRSDOS COMMENTED, the code at location 4400H is labelled "Twiddle some electronic thumbs." This is a delay routine for disk I/O. When the speed is changed to 4MHz, the time spent executing these instructions is cut by roughly one half and, on occasion — the disk becomes garbaged.

The method used to fix this was to substitute instructions that would take about twice as long, so that cutting the time in half would get it back to normal even though the CPU work was still faster.

To switch back to Model III speed, I replaced those original instructions. Examine the source listing for SPEEDSW/CMD. At lines 180-200, the code at the disk timing location (4400H) is loaded and compared to the value of the longer instructions. If the longer instructions are already there, they need to be replaced with the original shorter ones, so go to MKSHRT at line 330.

When the timing codes are the long ones, they are overlayed with shorter codes, two at a time, in lines 330-420. The count starts at eight, and is decremented by one, twice during each loop.

The only other possibility is that they are already the original ones, so make them longer at lines 210-270. It takes eight of them to cover up the old code. Notice that the count starts at eight and is decremented by one for each loop until the count is zero.

The assembly language equivalent of the PEEKing, ANDing and or ORing, and POKEing is done in two places. Depending on whether I am speeding up (ORing) or slowing down (ANDing), I execute the code at 280-320 or 430-470, respectively.

Each piece gets the old value, makes the changes, puts it back, outputs to the port, and returns to the calling program.

The /CMD file method has worked well for me, but I wanted to be able to change the speed on the fly from within BASIC. The load address of EDIOH was a good place for my use, but the code is location independent, so you

can move it anywhere.

The program can be loaded and jumped to in BASIC with CMD "L", "SPEEDSW/CMD", DEFUSRO=&HEDIO, X=USRO(0). Remember to protect high memory for the location you choose. It loads and runs a lot faster if it is resolved into decimal numbers and POKEd into a magic array. Magic arrays are strings you can execute. They have been explained in many 80-MICRO, Computer User, and Basic Computing articles, as well as BASIC Faster and Better.

00010: SPEEDSW - SWITCH MODEL 4 (IN III MODE) TO 4MHz **JANUARY 27,1984** 00020: PETE FRATUS 00030: USING THE CURRENT TIMING CODE AS A REFERENCE. 00040: PROGRAM TOGGLES BETWEEN III SPEED AND 4 SPEED. OOO50:I USE IAN WEBB'S METHOD OF DISK SLOW DOWN GOING OF MHz. AT 4400H. THERE IS SERIES 00060:TO ٨ INSTRUCTIONS HE REPLACES THEM WITH SLOWER 00070:TO PROVIDE DISK TIMING. WHEN GOING BACK TO III SPEED. 00080: INSTRUCTIONS. REPLACE 00090: PUT BACK THE ORIGINAL INSTRUCTIONS.

```
00100: *** NOTE *** THE FORMAT OVERLAY CONTAINS THE SAME SET
OO110:0F TIMING INSTRUCTIONS: I WOULD NOT RUN IN 4 SPEED
00120; WHEN FORMATTING!
00130:
OO140: THIS PROGRAM IS RELOCATABLE BECAUSE NO LOCAL STORAGE
00150:IS USED.
001601
00170
             ORG
                     OED10H
                                START LOCATION
                                GET TIMING INSTR
00180 START
             LD
                     A.(DISK)
00190
             CP
                     LONGER
                                :IS IT LONG?
                     Z, MKSHRT
                                IF YES, MAKE SHORTER
             JR
00200
00210
             LD
                     A.LONGER
                                :ELSE, GET LONG CODE
                                ISET HL TO CODE ADDR
00220
             LD
                     HL, DISK
                                SET LOOP COUNT
00230
             "LD
                     B. EIGHT
                                ; PUT IN LONG CODE
00240 LLOOP
             LD
                     (HL),A
                                : NEXT ADDRESS
00250
             INC
                     НL
                                ; COUNT - 1
00260
             DEC
                                LOOP UNTIL 8 ARE DONE
00270
             JR
                     NZ,LLOOP
                                :GET OLD SPEED
00280
             LD
                     A. (SPEED)
                                TURN 4 SPEED BIT ON
00290
             OR
                     BIT6
                                TELL CPU WHAT YOU DID
00300
             OUT
                    (PT236).A
                                PUT NEW SPEED BACK
00310
             L.D
                    (SPEED),A
                                GO BACK TO DOS OR BASIC
00320
             RET
00330 MKSHRT LD
                                GET SHORT CODE
                    DE.SHRTER
                                GET CODE ADDRESS
00340
             LD
                    HL, DISK
                                SET LOOP COUNT
00350
             LD
                    B.EIGHT
                                ; PUT SHORT CODE IN ADDR
00360 SLOOP
             LD
                    (HL),D
                               : NEXT ADDRESS
00370
             INC
                    HL
                                 :. COUNT - 1
00380
             DEC
00390
                               : PUT OTHER SHORT CODE IN
             LD
                   (HL),E
```

00400		INC	HL	; NEXT ADDRESS
00410		DEC	В .	; COUNT - 1 AGAIN
00420		JR	NZ,SLOOP	LOOP UNTIL 8 ARE DONE
00430		LD	A, (SPEED)	GET OLD SPEED
00440		AND	NOT6	; SET 4 SPEED BIT OFF
00450		LD	(SPEED),A	PUT NEW SPEED BACK
00460		OUT	(PT236).A	TELL CPU YOU DID IT
00470		RET		GO BACK TO DOS OR BASIC
00480	BIGHT	EQU	0008H	
00490	BIT6	EQU	0040H	;MASK 01000000
00500	NOT6	EQU	OOBFH	; MASK 10111111
00510	LONGER	EQU	00E3H	OPCODE EX (SP), HL
00520	SHRTER	BQU	OF5F1H	OPCODES PUSH AF, POP AF
00530	PT236	EQU	OOECH	;PORT 236
00540	SPEED	EQU	4210H	LOCATION OF SPEED BIT
00550	DISK	EQU	4400H	LOCATION OF TIMING CODE
00560		END	START	

# OF MANUALS AND MYSTERIES BY JOEL LEE

You just bought a beautiful new program. It does all those things you've been dreaming of doing, faster and better. It's supposed to do some things you HADN'T dreamt of doing. You boot up the program—ah-h-h, lovely. You open the manual.

An hour later you emerge from the murky depths of the manual shaking your head like a wounded buffalo. Your new program does all kinds of wonderful things, but——how do you achieve them? An Egiptologist would circle this manual 3 times before approaching it. Baffled and weary you pick up your favorite computer magazine and what luck! There, an advertisement for a book that explains the manual for your beautiful, new program. \$24.95, plus shipping and tax, but this is no time to be paltry.

Three weeks later the book arrives. You grab it like a cannibal siezing a shipwrecked sailor. Pages and pages AND pages of explanation. After a week and hours of study the program is working. But it limps, it sputters, it's not quite the beautiful thing it could be. Then your eye falls upon an ad in your second favorite computer magazine. You know the rest. You guessed it. You buy the book that explains the manual for your beautiful program. \$24.95. Plus \$4.90 shipping. Plus tax.

<Message from JIMDINK at SBUG-80 02/19/84 10:20:19>
RE: IS THERE A DISK EMULATOR FOR THE MODEL I?
Read command:

HAVE NEED TO FIND AND INSTALL A DISK EMULATOR ONTO MY MODEL I (LNW) AS THE TYPE OF OF WORK THAT I AM DOING ON SHORT LETTERS IS JUST TAKING 60% OF MY TIME TO DO NOTHING BUT MASHING FLOPPYS. HAVE NOT BEEN SUCESSFUL IN LOCATING THE REQUIRED MATERIAL FOR THE MODEL I. AM ALSO INTERESTED IN ANYONE'S OPINION ABOUT AND EXPERIENCE IN THE USE OF THESE DEVICES. IS THERE MORE THAN ONE AVAILABLE?

WOULD APPRECIATE A CALL AT (415) 493-9307 IF YOU HAVE ANY INFO. WOULD APPRECIATE A CALL AT (415) 493-9307 IF YOU CAN LEND SOME INSIGHT. SORRY, CAN'T BE AT TUESDAY NIGHT'S MEETING BECAUSE OF PRIOR COMMITTMENT.

YOUR THOUGTS PLEASE....

#### Read command :

<Message from JIMDINK at SBUG-80 02/19/84 10:27:17>
RE: REPAIRS OF TI SILENT 700 MODEL 743 KSR EIA/TTY
Read command:

WHOM CAN YOU RECOMMEND TO REPAIR TWO OF THE ABOVE ITEMS ON AN EXPEDITED OR ONE WEEK TURNAROUND BASIS?

ONE UNIT DID NOT RETURN AFTER A POWER OUTAGE AND I SUSPECT POWER SUPPLY PROBLEMS.

THE OTHER UNIT SEEMS TO HAVE A WEAK STAPPER MOTOR IN THE HEAD DRIVE MECHANISM AND NEEDS ADJUSTMENT IN THIS AREA.

IN ADDITION, THIS PERSON WANTS TO BUY AN ADDITIONAL SILENT 700 OR EQUIVALENT.

YOUR THOUGHTS TO: JIM DINKEY
......(415) 493-9307
.....ENTERED SUNDAY 10:40 AM
THANKS FOR YOUR HELP.

# Read command:

<Message from PHANTOM at SBUG-80 02/19/84 20:38:13>
RE: WHAT IS CREF80/CMD ?
Read command :

HI ALL.

CAN SOMEONE OUT THERE HELP ME AND TELL ME WHAT CREFSO/CMD IS AND HOW OR EVEN WHEN TO USE IT? I FOUND IT ON A DISK I PURCHASED AT THE SWAP MEET AND CAN FIND NO DOC ON THE PROGRAM. IF SOMEONE WOULD LEAVE ME A NOTE I WOUULD GREATLY APPRECIATE IT

THANKS PHANTOM ALIAS RICHARD

<Message from BENSING at SBUG-80 02/03/84 19:28:34>

RE: MODEL IV INTERNAL SPEAKER Read command:

I HAVE A FRIEND WITH A MODEL IV. HE HAS HAD IT SINCE THE BEGINNING OF JANUARY AND DOESN'T HAVE ANY DRIVES YET. RIGHT NOW HE HAS A QUESTION ABOUT THE INTERNAL SPEAKER. HOW IS THE SPEAKER ENABLED (OR DOES IT EVEN COME INSTALLED FROM THE SHACK) ?
ANYBODY GOT AN ANSWER ?

### BOB >BENSING<

#### Read command :

<Message from JIBBYTRM at SBUG-80 02/04/84 12:56:43>
RE: Visicalc for Newdos80
Read command:

# Help !!!

I have made the necessary Zaps to VC/cmd that were described in the Newdoa80 zap information but there seems to be a problem. When you get into the STORAGE section and want to scan the drives for files with /VC as the extent it doesn't find them. Are there zaps that will make this work ? Are there any other problems or Zaps that are not discussed in the Newdos80 zaps that are needed in VC/CMD for MODEL I. By the way, what are the differences between the MODEL III and MODEL I Visicalc programs ?? I don't want to use TRSDOS unless I have to.

Thanks All Jibbytrm

#### Read command :

<Message from ROGERAND at SBUG-80 02/04/84 15:27:14>
RE: MODEL 100 DISK
Read command:

I WAS IN A RADIO SHACK STORE TODAY AND THEY WERE TALKING ABOUT DISK DRIVES FOR THE MODEL 100. DRIVES WILL BE APPROX \$250.00 REQUIRED INTERFACE \$750.00

THE INTERFACE WILL ALLOW USE OF A VIDEO MONITOR. INTERFACE? SHADES OF MODEL 11

LAST WEEK AT THE SWAP MEET IN SAM MATEO I SAW A NEC NOTEBOOK COMPUTER HOOKED TO A DISK DRIVE AND RUNNING A COLOR MONITOR VIA AN INTERFACE.

I HOPE POPPA SHACK HAS SEEN FIT TO INCLUDE COLOR.

# Read command :

<Message from KURT at SBUG-80 02/05/84 15:11:22>

SOUTH BAY TRS-80 USERS GROUP

RE: MOD.3 to 4 CONVERSION Read command:

HAS ANYONE HAD A THREE COVERTED TO A 4 BY RS. IF SO HOW HAS IT WORKED??? BTC. PLEASE LET ME KNOW CURT SCHILD 448-0448

#### Read command :

<Message from IANWEBB at SBUG-80 02/05/84 17:22:21>
RE: MODEL 4 INFORMATION---3==>4 CONVERSION
Read command:

You don't have an internal speaker unless you have a disk machine with the Model 4. It is an addition that is put in when you upgrade to disk drives.

When R/S converts a Model III to Model 4, they use your Model III disk drives and controller. They replace everything else EXCEPT the case of your machine, so for all practical purposes, it IS a Model 4. You also have an advantage in that you have two internal supplies and the Model 4 has a power supply droop when you access disk drives which causes the CRT to shrink slightly. With the dual Model III supplies, this doesn't happen.

Why not talk to Bruce Carso at B&C Computervisions about a conversion. It is identical and cheaper.

#### Read command:

<Message from LNW2MDX at SBUG-80 02/05/84 17:43:47>
RE: AIR TOOLS
Read command:

IF ANYONE OUT THERE HAS ANY AIR TOOLS THAT ARE NOT NEEDED I WOULD BE IN THE MARKET FOR THEM IF THE \$ ARE RIGHT...
CALL ME AT 408 734-0898 OR LEAVE A MESSAGE ON THE BBS ASK FOR SAM.....

<< LNW2MDX >>

#### Read command:

<Message from RON at SBUG-80 02/06/84 13:38:24>
RE: HOLMES MOD 1 RS232 / LNW E/I MOD
Read command:

THE GUY WHO RUNS 'DISK BYTERS' BBS IN FREMONT GOT HOLMES COMPLETE E/I FOR MOD 1 BUT BAUD RATE IS SET BY DIP SWITCHES, MAKING HIS 1200/300 BAUD BBS NO LONGER PROGRAM SWITCHABLE TO 1200. THERE WAS AN ARTICLE ABOUT ADDING A CHIP TO THE LNW MOD 1 E/I (HAS SAME DIP SW.) TO MAKE BAUD RATE PROGRAMMABLE LIKE REAL R/S IN SOME MAGAZINE, BUT I CAN'T PIRD IT.

DOES ANYONE KNOW WHAT MAG/ISSUE?

#### Read command :

<Message from RON at SBUG-80 02/06/84 13:43:44>
RE: MOD 100 HOLMES STRINGY REVIEW
Read command:

I RAN INTO DAN ROBINSON WHO IS DOING THE REVIEW OF HOLMES STRINGY FLOPPY (\$350) FOR MOD 100. HE MENTIONED ONE POINT HE THOUGHT WAS "VERY" BAD: IT CAN ONLY SAVE/LOAD .DO TEXT FILES; "NO" .BA .CO YOU MUST SAVE THE BASIC AS ASCII FIRST &WAIT (A LONG TIME) FOR BASIC TO 'EAT' THE ASCII WHEN LOADING. (DEVICE CAME FROM 80 MICRO; REVIEW IS FOR THEM & INFOWORLD; DAN WAS AT SAN BRUNO TRS/IBM CLUB 1ST TH)

#### Read command :

<Message from RON at SBUG-80 02/06/84 13:54:50>
RE: 80 TRACK DBL SIDED \$149 NEW
Read command :

THERE'S ONE LEFT TM100-4 TANDON BARE DRIVE. \$149 (UNLESS PHANTOM DECIDES TO TRADE HIS TM100-2 FOR IT). WHITE FRONT (NOT BLACK).

# Read command:

<Message from GLENN at SBUG-80 02/06/84 15:48:14>
RE: BAUD RATE AND LNW E/I
Read command:

I can't remember which issue it was in (80 MICRO) BUT!! the mod as given was NOT COMPATIBLE with the RS method of changing baud rate.

Glenn

<Message from GLENN at SBUG-80 02/06/84 18:36:59>
RE: NEED HELP TESTING BBS
Read command:

I am testing a new (for me) BBS system -TBBS and need help testing it - if you can call between 7:00 and 9:00 tonight, I would appreciate it greatly. the number is (408) 942-8164 300 baud only.

# Read command :

<Message from GLENN at SBUG-80 02/08/84 18:54:37>
RE: STILL TESTING THE BBS
Read command:

I am still testing the TBBS system - it will be up from 8:00 p.m. to 8:00 a.m. tonight so please give it a call. The number is (408) 942-8164 - 300 baud only!!! the modem will answer 1200 baud but will be unable to communicate.

Glenn

# Read command :

<Message from IANWEBB at SBUG-80 02/10/84 21:27:55>
RE: SCHEMATIC/MANUAL FOR TM100-4
Read command:

DOES ANYONE HAVE A SCHEMATIC OR BOOK FOR THE 80 TK DOUBLE SIDED TANDON TM100-4? WOULD SURE LIKE TO BORROW IT. IAN - 867-9533.

#### Read command :

<Message from IANWEBB at SBUG-80 02/10/84 21:29:49>
RE: DRIVES FOR \$25 AND \$75.
Read command:

WW SURPLUS/ COMPONENT SALES ON JUNCTION AVENUE ABOUT ONE BLOCK SOUTH OF BROKAW HAS MPI B-51 DRIVES.
\$25 EACH FOR AS-IS NEED REPAIR, BUT ALL THERE.
\$75 EACH FOR CHECKED OUT AND GUARANTEED 90 DAYS.
HAD A LOT OF THEM, BUT IF YOU WANT TO TRY TO MAKE A GOOD ONE OUT OF A COUPLE OF BAD ONES, PROBABLY SHOULD LOOK AT THEM SOON.

<Message from IANWEBB at SBUG-80 02/15/84 05:40:39>
RE: MODEL III FOR SALE + MX 80
Read command:

I know someone with a little-used Model III and MX80 which he wants to sell. Has used them less than 25 hours all total probably. Is interesting in selling the pair. Asking \$1400, but will discuss price.

Call (evenings probably best) 246-8984.

#### Read command:

<Message from BARRY at SBUG-80 02/15/84 08:28:13>
RE: DYNAMIC MEMORIES VIA BBS
Read command:

How about putting DYNAMIC MEMORIES onto a disk for down-loading? In that way SBUG can save the cost of mailing to those of us who would just as soon take MEMORIES of the board. Anyone else have any thoughts on this???

#### BARRY

#### Read command:

<Message from PHANTOM at SBUG-80 02/15/84 09:30:49> RE: FOR SALE 6800 SWTPC FLEX SYSTEM Read command :

Hi all.

I have for sale a good starter system. It is not a glamorous TRS-80 but it is a disk based system. I would recommend it for a hardware type person. It is complete with all the hardware documents spare memory boards and parts and pieces would cost \$\$ if purchased seperately. I am asking about \$650.00. I have voice synthesizer for it also. 6800 24k memory 5 RS232 ports 1 parrallel VS-SC01 DISK

software and more call for details.

Phantom Alias Richard at 984-8779 or 248-8770 work

#### Read command :

<Message from SAMBROWN at SBUG-80 02/18/84 10:34:17> Read command :

HI, I HAVE RECEIVED THE IBM TO TRS-80S AND VICE-VERSA PROGRAM AND IT ALSO CONTAINS THE COCO TO TRS-80S PROGRAM WITH IT. IT WORKS WELL AND IS WORTH THE 54.00\$ SPENT. BUT A WARNING TO THE COCO PEOPLE::::IT DOES NOT TAKE TAKE THE COCO TO IBM AS ADVERTISED::::::: THIS WAS ADVERTISED VERY HEAVILY AND THEY THOUGHT IT COULD BE DONE, AT ADVERTISENG TIME IT WAS PUBLISHED THAT WAY. DONT BUY IT FOR TRYING TO USE WITH THE IBM-COCO. IT HANDLES BOTH MS-PC DOS 1.0 VERY WELL AND BRINGS THE OLD MODEL 1-3 UP WITH THE NEW MACHINES IT DOES HAVE HARDWARE RESTRICTIONS.

#### Read command:

<Message from SAMBROWN at SBUG-80 02/18/84 10:37:16> Read command :

WE RECEIVED THE LATEST VERSION OF HYPERZAP 3.0 AND ITS WELL WORTH THE 15.00\$. IT MAKES MOST OF THE MANUAL COMMANDS AUTOMATIC AND LISTS THE RESTRICTIONS OF THE PROGRAM TOO. IT DOES HAVE A LOT OF OTHER FUNCTIONS TOO.

# Read command :

<Message from SAMBROWN at SBUG-80 02/18/84 10:42:29> Read command :

IF YA ALL NEED DOCUMENTATION OR PROGRAMS AND CANT FIND ANY ARROUND THE CLUB, YA MIGHT GIVE ME A CALL. WE DO HAVE THE LARGEST SELECTION OF TRS-80 PROGRAMS AT THE HOUSE, AND WILL ALWAYS BE WELCOME TO USE THEM. IT DOES NOT MEAN YA HAVE TO AFFILIATE YOURSELVES WITH MY CLUB IM STILL A

SOUTH BAY TRS-80 USERS GROUP

MEMBER IN GOOD STANDING WITH S-BUG. AS A MEMBER SINCE 1979 I HAVE A WIDER VIEW OF THE CLUB AND ITS CAPABILITIES. CALL IF YA CANT FIND YOUR PROGRAMS OR DOCUMENTATION, I'LL BE GLAD TO SHARE WITH YA.

#### Read command :

<Message from MARRAZZO at SBUG-80 02/18/84 17:36:28>
RE: VIDEO GAME
Read command:

HELLO I JUST WENT THROUGH MY JUNK AND FOUND A BALLEY ARCADE GAME WITH SEVEN CART.

ONE OF THEM IS THE BASIC CART. IF ANYONE IS INTERESTED IN IT GIVE ME A CALL AT HOME THE NUMBER IS 238-5189. I AM ASKING 50.00 FOR IT. IF I REMEMBER RIGHT IT HAD SOME PROBLEM RUNING AFTER IT WARMED UP. BUT AT 50.00 YOU MAKE IT RUN JOE MARRAZZO (MARRAZZO)

I am still testing the TBBS system - it will be up from 8:00 p.m. to 8:00 a.m. tonight so please give it a call. The number is (408) 942-8164 - 300 baud only!!! the modem will answer 1200 baud but will be unable to communicate.

Glenn

# Read command:

<Message from IANWEBB at SBUG-80 02/10/84 21:27:55>
RE: SCHEMATIC/MANUAL FOR TM100-4
Read command:

DOES ANYONE HAVE A SCHEMATIC OR BOOK FOR THE 80 TK DOUBLE SIDED TANDON TH100-4? WOULD SURE LIKE TO BORROW IT. IAN - 867-9533.

#### Read command :

<Message from IANWEBB at SBUG-80 02/10/84 21:29:49>
RE: DRIVES FOR \$25 AND \$75.
Read command:

WW SURPLUS/ COMPONENT SALES ON JUNCTION AVENUE ABOUT ONE BLOCK SOUTH OF BROKAW HAS MPI B-51 DRIVES. \$25 EACH FOR AS-IS NEED REPAIR, BUT ALL THERE. \$75 EACH FOR CHECKED OUT AND GUARANTEED 90 DAYS. HAD A LOT OF THEM, BUT IF YOU WANT TO TRY TO MAKE A GOOD ONE OUT OF A COUPLE OF BAD ONES, PROBABLY SHOULD LOOK AT THEM SOON.

<Message from IANWEBB at SBUG-80 02/15/84 05:40:39>

RE: MODEL III FOR SALE + MX 80 Read command :

I know someone with a little-used Model III and MX80 which he wants to sell. Has used them less than 25 hours all total probably. Is interested in selling the pair. Asking \$1400, but will discuss price.

Call (evenings probably best) 246-8984.

# Read command :

<Message from DURANT at SBUG-80 02/23/84 17:58:17>
RE: MODEL I WANTED
Read command:

### H1 A11

A friend of mine is looking for a Model I, Level II Machine with a 'G' board (one with two rom chips). If you have one for sale for or know of someone who does please give John Rovner (415) 489-4058 a call. He can be reached at this number any day after 2 P.M.

John Durant (Durant)

# Read commend :

<Message from MANGR at SBUG-80 02/23/84 18:58:15>
Read command :
ANYONE THAT MAY HAVE DOCUMENTATION ON PROFILE V3.2 PLEASE
CALL JIM, (408) 246-5286

#### Read command :

<Message from ROGERAND at SBUG-80 02/24/84 21:43:56>
RE: DRIVES FOR SALE
Read command :

A PRIEND HAS THE FOLLOWING FOR SALE.

2---5 1/4 DOUBLE DENSITY SINGLE SIDED
BASF DRIVES

1---PERCOM SEPERATOR FOR MODEL I
(THIS IS NOT A DOUBLER)

#### Read command :

<Message from ROGERAND at SBUG-80 02/24/84 21:45:37>
RE: 0000PS MORE ABOUT PREVIOUS MESSAGE. THE SELLER, ROBERT HANSLEMANN (415)591-1193

From Editor: The Computer Faire RAG has a good article on public domain software on page 5. It might be interesting to see how much of that mentioned in the article we have and to make an effort to obtain what we do not have.

South Bay TRS-80 Users Group P.O. Box 60116 Sunnyvale, Ca 94088

FIRST CLASS MAIL